

PAIWebStore.com

Your Online Source for ATM Parts/Supplies and Repair



SHIP ALL ITEMS FOR REPAIR TO:

PAI ATM Services Group
200 Briarwood West Dr.
Jackson, MS 39206
Attn: Repair Dept.



To obtain a RMA#, Call 800.523.2104

Repair Cost

TRITON	
Model Dispensers	
SDD Controller Board	\$95.00
SDD1700 Dispenser*	\$250.00
SDD1700 Dispenser Rebuild	\$379.00
SDD1700 Cassette	\$150.00
TDM100/150 Dispenser*	\$199.00
TDM100/150 Cassette (includes replacing the picker assy)	\$120.00
TDM150 Dispenser w/Extension (Billfish)*	\$250.00
Mako Dispenser*	\$300.00
Mech 10 (MiniMech) Dispenser*	\$250.00
Model 91XX	
91XX Mainboard Mono without speech, without modem	\$120.00
91XX Mainboard Mono with speech, without modem	\$144.00
91XX Mainboard Color without speech, without modem	\$128.00
91XX Mainboard Color with speech, without modem	\$144.00
9100 Printer with cutter	\$76.00
9100 Power Supply Mini-Mech	\$84.00
9100 Power Supply for TDM	\$84.00
9100 Power Supply with Fan Assembly TDM	\$95.00
Model 96XX	
96XX Printer Controller Board	\$120.00
96XX Printer with Cutter	\$192.00
96XX Printer with/Cutter and Control Assembly	\$312.00
96XX CPU Module	\$76.00
96XX Memory Module (U.S.)	\$100.00
96XX Memory Module Assembly;	\$100.00
96XX 2400 Baud Modem/LCD Module (Color-256)	\$188.00
96XX 33,600 Baud Modem/LCD Module (Color-256)	\$188.00
96XX 2400 Baud Modem/LCD Module (Mono)	\$148.00
96XX 14,000 Baud Modem/LCD Module (Mono)	\$148.00
96XX 33,600 Baud Modem/LCD Module (Mono)	\$148.00
96XX Memory Expansion Bd. 1 MB	\$76.00
Model 97XX	
97XX Main Board	\$216.00
Power Supply for (TDM and Mech 10)	\$84.00
Power Supply for (SDD and NMD50)	\$84.00
RL/FT/RT	
RL/FT/RT X-Scale Main Board	\$316.00

PAIWebStore.com

Your Online Source for ATM Parts/Supplies and Repair



SHIP ALL ITEMS FOR REPAIR TO:

PAI ATM Services Group
200 Briarwood West Dr.
Jackson, MS 39206
Attn: Repair Dept.

To obtain a RMA#, Call 800.523.2104



	Repair Cost
HYOSUNG	
1K Note CDU*	\$249.00
2K Note CDU*	\$299.00
1K/2K Note Cassette	\$150.00
1K/2K Note Cassette (includes replacing the picker assy)	\$225.00
1K Drawer Style CDU*	\$250.00
4K Note CDU*	\$350.00
1000/2000/2100 Printer Assy	\$150.00
15xx Printer Assy	\$175.00
1000/15xx/2xxx Main CE (excluding the ARM9 board)	\$145.00
1000/15xx/2xxx CDU Main CE (short board only)	\$115.00
1000/15xx/2xxx Power Supply	\$125.00
15xx Card Reader	\$65.00
1000/15xx/2xxx Printer PCBs	\$115.00
1000/15xx/2xxx Modem CE	\$75.00
TRANAX	
TCDU Dispenser*	\$239.00
MCDU Dispenser*	\$289.00
TIDEL	
IS-1000/2000 Main CE	\$145.00
IS-1000/2000 Power Supply	\$95.00
SOFTWARE LOAD	
Software Load/Flash Update Only	\$75.00

*Price does not include dispenser mainboard repair. Add \$75 if board requires repair.

We do not repair parts that have rodent damage.

Don't forget to ask about our
PRICE MATCH GUARANTEE*
on all of our ATM Part Repairs!

*Subject to restrictions. Call for details.